

400 North Capitol Street, N.W. Washington, D.C. 20001 ngvamerica.org



**To**: Compressed Natural Gas Vehicle Station Owners & Operators

**From**: NGVAmerica Technology & Development Committee

Date: December 12, 2016

Subject: Technology Bulletin - Compressed Natural Gas Station Incident

It is recommended that all CNG owners and operators of CNG fueling stations conduct an inspection and review of CNG dispensers manufactured prior to 2006. This effort should be coordinated with your CNG dispenser manufacturer/supplier to ensure that you are aware of any opportunities to upgrade equipment which might help to ensure continuous dependable and secure operation.

The NGVAmerica Technology & Development Committee was made aware of an incident that occurred at the Lambert/St. Louis International Airport involving a Compressed Natural Gas (CNG) dispenser. The incident occurred on June 23, 2015 while the dispenser was idle. The Micro Motion CNG050 flow meter within the dispenser lost primary containment, due to external factors, causing a rupture of the device. The vintage of the flow meter did not have a pressure relief feature which now is integrated into the design and into to the design of other manufacturer's flow meters. There have been no other such incidents reported.

For any questions relating to this bulletin, please contact NGVAmerica Technology & Development Director, Dan Bowerson at <a href="mailto:dbowerson@ngvamerica.org">dbowerson@ngvamerica.org</a>.

## NOTICES AND DISCLAIMER:

NGVAmerica has taken great effort to ensure the accuracy and reliability of the information contained in this document; however, this document is provided "as is" and neither NGVAmerica nor its employees or agents make any representation, warranty or guarantee in connection with this document, express or implied. NGVAmerica and its members companies disclaim liability for any personal injury, property or other damages of any nature whatsoever, whether special, indirect, consequential or compensatory, directly or indirectly resulting from the publication, use of, or reliance on this document. Nothing contained in this document should be viewed as an endorsement or disapproval of any particular service provider or products. The information contained in this document is not intended as legal advice. Questions regarding this document should be sent to: NGVAmerica, 400 N. Capitol St., N.W., Suite 450, Washington, D.C. 20001.